COBRA[®] 23801 E. La Palma Ave., Yorba Linda, Ca 92887 Ph. 714.692.8180 Fax. 714.692.5016

Items Supplied >

1 - Front Muffler

1 - Rear Muffler

2 - #268-55 T-Bolt Clamps

1 - Mounting Bracket Assembly w/hardware

Application >

YAMAHA ROADSTAR 1600/1700 99-14

www.cobrausa.com

| Instruction Manual > | | | | 2171SC | Page 1 of 1 | |
|----------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------|-------------------------|------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------|--|
| | | LATION, MAKE SURE YOUR TS AS TO THEIR CONDITION, | | K GASKETS ARE IN GOOD SH ACE THEM. | APE. IF YOU | |
| | Read all instructions carefully and completely before installing your new exhaust system | | | | | |
| 1. | Remove the stock | tock mufflers leaving head pipes in place. | | | | |
| 2. | Install the supplied mounting bracket on top of the original mounting bar with the bend going out and down using the two original mounting bolts. | | | | | |
| 3. | Slip the rear muffler body onto the head pipe. Mount the muffler body bracket to the rear slotted hole on the mounting bracket using the supplied nut, bolt, and washers. Tighten the T-bolt clamp then the mounting hardware. | | | | | |
| 4. | | | | muffler body bracket to the front rs. Tighten the T-bolt clamp then | | |
| | IMPORTANT: | RoadStar 1600 ('99-'03) part recommended that you insta | #92-2 II a Co | ur bike with a Cobra Jet Kit, avail 271, RoadStar 1700 ('04-'07) pa bra Fi2000® Digital Fuel Proce padstar 1700 part #92-1771CL | art #92-2272. It is essor with your Cobra | |
| | Before starting your engine remove all fingerprints from chrome with a quality wax or chrome polish. Failure to do so can cause discoloration. Due to fluctuations in carburetor settings, timing, etc., Cobra Engineering does not warrant against chrome discoloration. | | | | | |
| | | | | ns that remove original equipment Executive Order for that system | | |
| | | | | . Please never operate your mo of your motorcycle and please | | |